

No. ST/1509

Dated: 14-12-2023

**TO WHOM IT MAY CONCERN**

It is certified that I have personally visited the school buildings of "Shishu Niketan Model Sr. Sec. School" at Sector- 22D, Chandigarh . The inspection was carried out along with the Director of school Mr. Rakesh Khurana.

The School building has been constructed as a Composite structure building (i.e. with load bearing walls and intermittent RCC Columns) . The building was started in year 1979, so all buildings have been constructed as per old codal provisions. The Plot area of the building is 123473 sft and the approx. covered area is 67008 sft of three stories with part Basement (Basement: 2172 Sft, GF: 23206 sft, FF: 22730 sft , TF: 18900 sft).

On the visual inspection there were no major structural/deflection cracks observed. Minor cracks had appeared on the Junction of RCC Slab and brickwork, which the management was intimated. Rebound hammer tests and Ultrasonic pulse velocity was also carried out to determine the strength of concrete.



1 **STRUCTURAL STABILITY CERTIFICATE**

As on date the buildings is fit for running an educational institute ,  
provided it is properly maintained and retrofitted. The validity of this  
certificate is one year .

**For M/s Continental Foundations**



**"PICTURE OF SHISHU NIKETAN MODEL  
SR. SEC. SCHOOL, CHANDIGARH"**

*Handwritten signature*

